,07/01/20

Date:

Monday, 26/02/2007 8:25:35 AM

User:

Linda Lacelle

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 30970

**Estimate Number** P.O. Number

: 10366 All:

This Issue Prsht Rev.

: 26/02/2007

: 30920

**Previous Run** 

First Issue

Written By

Checked & Approved By

Comment

: Est Rev: A 05.10.13 New Issue KJ/JLM 06-06-08 As per DSI9336 JLM Est Rev:B

S.O. No. : 11A

: LANDING GEAR

Material **Due Date** 

**Drawing Name** 

**Part Number** 

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

: 05/03/2007

: N/A

: D412742013

: UNDER REVIEW

: FLOAT SKIDTUBE

Qty:

1 Um:

Each

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description: DOCUMENT CONTROL

1.0

Comment: DOCUMENT CONTROL

Photocopy bluefile and create labels per PPP D412-742-013

FLOAT SKID ASSEMBLY

2.0



Comment: Sub-Component FLOAT SKID ASSEMBLY D412-742-043 B 276(4

3.0 D2571

Saddle, Fwd, Out



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Qty Part Number

1 D2571

Description

Saddle Fwd Outside

Batch 32<u>63 44</u> V

4.0

D2572

Pick:

Saddle, Fwd, In



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

**Qty Part Number** 

1 D2572

Pick:

Description

Saddle Fwd Inside

Date: Monday, 26/02/2007 8:25:35 AM Linda Lacelle User: **Process Sheet Drawing Name: FLOAT SKIDTUBE** Customer: CU-DAR001 Dart Helicopters Services Job Number: 30970 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** D2573 Saddle, Aft, Out 5.0 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Description **Qty Part Number** Saddle Aft Outside 1 D2573 D2574 6.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description **Qty Part Number** Saddle Aft Outside 1 D2574 D2747 7.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Description **Qty Part Number** D2747 Bolt 8.0 D2876 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: Pick: Description Batch **Qty Part Number** 28016 Saddle Spacer 2 D2876 D2877 Saddle Spacer 9.0 2.0000 Each(s)/Unit Total: Comment: Qty.: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D2877 Saddle Spacer D34031 10.0 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description Batch
Bushing B28320 V **Qty Part Number** 16 D3403-1

Page 2

Form: rorocess

Date: Monday, 26/02/2007 8:25:35 AM User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 30970 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** Bushing D34033 11.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description B30922V Batch 8 D3403-3 Bushing\_ D3405041 Lug Assembly 12.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description **GHW** Lug 1 D3405-041 D3405043 13.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Description **Qty Part Number** D3405-043 **GHW** Lug 14.0 AN4C6A 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 16 AN4C6A 15.0 AN4C46A Comment: Qty.: 4.0000 Each(s) 4.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description 4 AN4C46A 16.0 AN4C52A Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description M100340 s 8 AN4C52A Bolt

Date: Monday, 26/02/2007 8:25:35 AM User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 30970 Part Number: D412742013 Job Number: Seq. #: Description: Machine Or Operation: BOLT 17.0 AN6C12A Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: 1101467 **Qty Part Number** Description 8 AN6C12A AN960C416L 18.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Pick: **Qty Part Number** Description M100851 32 AN960C416L Washer 7707 19.0 AN960C616L WASHER 8.0000 Each(s) Comment: Qtv.: 8.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description 8 AN960C616L Washer WASHER 20.0 AN960C716L Comment: Qty.: 16.0000 Each(s) 16.0000 Each(s)/Unit Total: Pick: M102029 **Qty Part Number** Description 16 AN960C716L Washer 21.0 MS210434 Nut Comment: Qty.: 29.0000 Each(s)/Unit Total: 29.0000 Each(s) Pick: **Qty Part Number** Description 29 MS21043-4Nut 1102404 .

Date: Monday, 26/02/2007 8:25:35 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: FLOAT SKIDTUBE Job Number: 30970 Part Number: D412742013 Job Number: Seq. #: Description: Machine Or Operation: Inventory 22.0 NAS1515H4L 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 32 NAS1515H4L Washer NAS1515H6L 23.0 Inventory 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: Pick: Description Qty Part Number Washer <u>1189/8</u> 8 NAS1515H6L 24.0 NAS1515H7L Inventory Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description Washer 17/00727 16 NAS1515H7L 25.0 D3407041 Tow Ring Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Description **Qty Part Number TOW RING** D3407-041 26.0 D34173



2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: Pick:

Batch 7644 <u>J</u> **Qty Part Number** Description D3417-3 WASHER

Date: Monday, 26/02/2007 8:25:35 AM User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 30970 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** D34561 washer 27.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Batch WASHER D3456-1 28.0 AN4C7A Comment: Qty.: Total: 4.0000 Each(s) 4.0000 Each(s)/Unit Bolt Batch: <u>110142</u>7 QC4 INSPECT 100% KITS FOR COMPLETENESS 29.0 S FOR COMPLETENESS Comment: INSPECT PACKAGING RESOURCE #1 PACKAGING 30.0 CHG OUD Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-013 + DSI 9364 \*\* Location: PH 07.02.26 FINAL INSPECTION/W/O RELEASE 31.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion